

Site: Nieman's Service Station, PECFA#54495-2287-41, BRRS#03-72-001242

1. The vertical extent of groundwater contamination has not been defined. Does this need to be completed?

There is sufficient definition of the contaminant zones at this site.

2. Does the soil contamination at B-2 need to be addressed?

Soil remediation has been completed to the extent practicable.

3. Should the recovery wells be pumped periodically?

Groundwater samples have not been collected from the wells on site in over a year and a half. The present groundwater contaminant conditions are unknown. The need to pump the recovery wells will be dependent upon subsequent groundwater sampling results which includes depth of free product if present.